



2008 HONDA FIT

Report verified by JP Center

3.5

Condition

VEHICLE DETAILS

Lot number

3067

Auction

KCAA Fukuoka

Auction date

2013-04-11

Chassis ID

GE6

Vendor

HONDA

Model

FIT

Mileage

73 000 km

Engine CC

1300

Year

2008

Grade

13L

Inspection

Equipment

AC

Transmission

FAT

Awd

N/A

Start price

180000 YEN

Finish price

363000 YEN

Color

BLUE

Condition

3.5

Status

unsold

Chassis

GE6-1068345

CONDITION SHEETS & PHOTOS

Chassis ID

GE6

Vendor

HONDA

Model

FIT

Mileage

73 000 km

Engine CC

1300

Year

2008

Grade

13L

N/A

Start price

180000 YEN

Finish price

369000 YEN

Color

BLUE

Condition

3

Status

unsold


Chassis

GE6-1068345

CONDITION SHEETS & PHOTOS

出品 No	0197			総合	外装	内装
初年度登録	車名	排気量	グレード	燃料	ドア形状	
20 03	フィット	1300	13L	G	5DHB	
年 月		CC				
シフト	色	内装色	車検	走行	推定	冷房
FAT	カーNo BG53M ブルー	カーNo		73,403	Km	A/C
		年 月		千Km		
型式	定員	人	モデル年	ハンドル	輸入	装備品
DBA-GE6		t				PS PW I7B ABS
リサイクル預託額	保証書	ステッカー	名変期限	NOx・PM	セルストップ	ガラス
10,810	有	無	月	日迄		
車歴	自家用			A キズ	U 凹	B 傷凹
登録 No				P 要塗装	W 補修跡	
車台 No	GE6-1068345			S サビ	C 腐食	G 飛石傷
				X 要交換	XX 交換	

- *特記事項*
- AA初
 - 室内ノーマルタイヤ有(夏)
 - Fサイドメンバー凹み
 - コアサポート凹み
 - 社外AW?
 - ネジ止アッパーコア交換
 - スタッドレスタイヤ
 - バンク修理キット有
 - Fハンパーホースノット交換
 - シート 汚れ
 - シート シミ小
 - 天張 うすい汚れ
 - 外装うすい線キズ





CONDITION LIST EXPLANATION

A1: Small Scratch
A2: Scratch
A3: Big Scratch
B: Dent with scratch
B1: Distortion on (radiator) core support or back panel (approximately size of a thumb)
B2: Big Distortion on (radiator) core support or back panel
B1-B4: Large dents
C1: Corrosion
C2: Heavy Corrosion
AU2: Dent and Scratch (Medium)
E1: Few Dimples
E2: Several Dimples
E3: Many Dimples
G: Stone chips in glass
H: Paint faded or (Thumb size hole from rust, corrosion or rotting)
P: Paint damaged marked

S1: Rust
S2: Heavy Rust
U1: Small Dent
U2: Dent
U3: Big Dent
Y1: Small Hole or Crack
Y2: Hole or Crack
Y3: Big Hole or Crack
X1: Small Crack on Windshield (approximately 1cm)
R: Repaired Crack on Windshield
RX: Repaired Crack on Windshield (needs to be replaced)
X: Needs to be replaced or crack on glass
XX: Replaced
W1: Repair Mark/Wave (hardly detectable)
W2: Repair Mark/Wave
W3: Obvious Repair Mark/Wave (needs to be repainted)

AUCTION GRADE EXPLANATION

6/S New car

5 Used but appears as new

0 Repaired

R Repaired (History of being repaired, parts replaced, no quality guarantee, buy at your risk, could be big damages, frame bent possibility.)

4.5 Very clean with only minor pin dents & scratches

4 Good condition with normal wear & tear

3.5 Numerous condition faults / possible minor repair

3 Poor condition / noticeable dents & damage / rust / past repair

2 Very poor condition / water damaged

RA Accident repaired, been in crash, parts replaced, generally small damages.

***** Ungraded (existing fault / damage)**

A - D Body / interior condition (**A – as new**, **B – very clean**, **C – average**, **D – poor**)

E – The car is in bad shape. Rust, corrosion and exterior breakdowns are plenty

1 Modified (usually performance parts)

JP AS

© 2025 JPAS. All rights reserved.

<https://jpauctionsheet.com>